

Make Ready Checklist Inspection

Inspection Date	Technician	Property	Units
06-15-2021	Lauren Pray	York North (YONO)	0221

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident

Lindy Community Representative Name	Lauren Pray
-------------------------------------	-------------

Technician Lauren Pray

Resident not available for signature

Resident refused Signature