



## Make Ready Checklist Inspection

Inspection Date	Technician	Property	Units
06-19-2021	Kim Crawford	York House (South)	0809

DINING ROOM:	
Ceilings / Lights:	Not Ok
Charges Type	
Charges	0

BATHROOM:	
Ceiling Lights:	Not Ok
Charges Type	
Charges	0
Other:	Not Ok
Charges Type	
Charges	0
Comment	Replace toilet seat

Resident	
----------	--

Lindy Community Representative Name	Kim Crawford
-------------------------------------	--------------



Technician	Kim Crawford
Resident not available for signature	
Resident refused Signature	