



Make Ready Checklist Inspection

Inspection Date	Technician	Property	Units
06-19-2021	Kim Crawford	York House (South)	0707

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident	
----------	--

Lindy Community Representative Name	Kim Crawford
-------------------------------------	--------------

Technician	Kim Crawford
Resident not available for signature	
Resident refused Signature	