

## **Move Out Inventory & Condition Form**

<b>Inspection Date</b>	Technician	Property	Units
06-22-2021	Antonio Cordero	Gateway Towers	C212

Resident Name	Yassine Jnah
Forwarding Mailing Address	3011 Devereax Ave., Philadelphia PA 19149
Date Resident Turned in Keys	06-18-2021

	Damage Summary			
Main Category	Sub Category	<b>Charges Type</b>	Note	Charges
LIVING ROOM	Walls / Outlets	Repair	Minor wall damage in near kitchen.	\$20.00
Additional Dam	age Charges			
			Total Charges	\$20.00

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Walls / Outlets:	Not Ok
Charges Type	Repair
Charges	
Comment	Slight damage to the right of the door kitchen exterior wall



Window:	Ok	
Window coverings:	Ok	

D 1		
Reside	,	

Lindy Community Representative Name  Antonio Cordero
--

Technician	Antonio Cordero
Resident not available for signature	YES
Resident refused Signature	NO