

Move Out Inventory & Condition Form

Inspection Date	Technician	Property	Units
06-30-2021	Antonio Cordero	Gateway Towers	B420

Resident Name	Maria Albanese
Forwarding Mailing Address	Not Available
Date Resident Turned in Keys	06-26-2002

Damage Summary				
Main Category	Sub Category	Charges Type	Note	Charges
LIVING ROOM	Other	Replace	holes in wall	\$60.00
LIVING ROOM	Walls / Outlets	Repair		\$0.00
Additional Dam	age Charges			
Large sofa left in	living room			\$200.00
			Total Charges	\$260.00

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Not Ok
Charges Type	Replace
Charges	
Comment	Has sofa and living room



Walls / Outlets:	Not Ok
Charges Type	Repair
Charges	
Comment	And one wall has holes from TV stand



Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

KITCHEN:		
Backsplash:	Ok	
Cabinets:		
Cabinet Door:		Ok
Cabinets:		
Cabinet Handle:		Ok

Cabinets:		
Cabinet Shelf:	Ok	
Ceiling Fan:	Ok	
Ceiling Light Fixture:	Ok	
Ceiling Lights:	Ok	
Cleaning of Stove:	Ok	
Counter Top:	Ok	
Dishwasher:		
Dishwasher Knob:	Ok	
Dishwasher:		
Dishwasher Rack:	Ok	
Dishwasher:		
Dishwasher Silverware Holder:	Ok	
Drip Pan:	Ok	
Electric Meter:	Ok	
Faucet:	Ok	
Faucet Knobs:	Ok	
Fire Stops:	Ok	
Floors:	Ok	
Formica/Tiles:	Ok	
Garbage Disposal:	Ok	
Kitchen Sink:	Ok	
Microwave:	Ok	
Other:	Ok	
Oven / Range:		
Oven Cleaning:	Ok	
Oven / Range:		
Oven door handle:	Ok	
Oven / Range:		
Oven drip pan:	Ok	

Oven / Range:	
Oven knobs:	Ok

Oven / Range:	
Oven Racks:	Ok

Oven / Range:	
Range burners:	Ok

Oven / Range:		
Range Hood:	Ok	
Oven Door Handle:	Ok	
Oven Racks:	Ok	
Range Top: Ok		
Refrigerator (Freezer): Ok		
Rubber Stopper:	Ok	
Stove Knob:	Ok	
Wall Outlets:	Ok	
Washer/Dryer:	Ok	
Window Coverings:	Ok	

BEDROOMS:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Floors / Carpet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Comment	Walls have screw holes in second bedroom from TV



Window:	Ok	
Window coverings:	Ok	

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Ok
Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Ok
Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Ok
Tub Knob(s):	Ok
Tub Reglazing:	Ok
Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok

Fix Door when extra lock is removed:	Ok	
Mail-Box Lock:	Ok	

DOORS:	
Apartment Door:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

PAINTING:	
Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident				
----------	--	--	--	--

Lindy	Community	Re	presei	ntative	Name
Liliay	Community	110	br cocr	ILLULIVC	TTUILL

Antonio Cordero

/		1	
		1	
V	V		Ny
		V	

Technician	Antonio Cordero
Resident not available for signature	YES
Resident refused Signature	NO