

## **Move Out Inventory & Condition Form**

Inspection Date	Technician	Property	Units
08-04-2021	Antonio Cordero	Gateway Towers	A101

Approved By	Marva Brown
Resident Name	Sherrie Shillingford
Forwarding Mailing Address	Not Available
Date Resident Turned in Keys	08-01-2021

Damage Summary				
Main Category	Sub Category	Charges Type	Note	Charges
LIVING ROOM	Walls / Outlets	Repair		\$0.00
Additional Damage Charges				
Bedroom carpets torn and heavily soiled with pet urine/sub floor needs treating		\$250.00		
		To	otal Charges	\$250.00

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Walls / Outlets:	Not Ok
Charges Type	Repair
Charges	
Comment	Paint holes on left side of living room and wall have been patched



Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

KITCHEN:		
Backsplash:	Ok	
Cabinets:		
Cabinet Door:		Ok
Cabinets:		

Ca	abinets:	
Ca	abinet Handle:	Ok

Cabinets:		
Cabinet Shelf:		Ok
Ceiling Fan:	Ok	
Ceiling Light Fixture:	Ok	
Ceiling Lights:	Ok	
Cleaning of Stove:	Ok	
Counter Top:	Ok	
Dishwasher:	Ok	
Drip Pan:	Ok	
Electric Meter:	Ok	
Faucet:	Ok	

Faucet Knobs: Ok		
Fire Stops: Ok		
Floors: Ok		
Formica/Tiles:	Ok	
Garbage Disposal:	Ok	
Kitchen Sink:	Ok	
Microwave:	Ok	
Other:	Ok	
Oven / Range:		
Oven Cleaning:	Ok	
Oven / Range:		
Oven door handle:	Ok	
Oven / Range:		
Oven drip pan:	Ok	
Oven / Range:		
Oven knobs:	Ok	
Oven / Range:		
Oven Racks:	Ok	
Oven / Range:		
Range burners:	Ok	
Oven / Range:		
Range Hood:	Ok	
Oven Door Handle:	Ok	
Oven Racks:	Ok	
Range Top:	Ok	
Refrigerator (Freezer):	Ok	
Rubber Stopper:	Ok	
Stove Knob:	Ok	
Wall Outlets:	Ok	

BEDROOMS:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Floors / Carpet:	Ok
Comment	Carpets are ruined pet stains and holes in carpet



Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Ok
Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Ok
Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok

Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Ok
Tub Knob(s):	Ok
Tub Reglazing:	Ok
Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok


KEYS:		
Failure To Return Apartment Key:	Ok	
Failure To Return Mailbox Key:	Ok	

DOORS:	
Apartment Door:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

PAINTING:	
Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

CARPET:
---------

Burns:	Ok
Deodorize:	Ok
Comment	Carpet has pet stains holes and needs to be replaced



Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok
Comment	Master bedroom carpet stains all over pet stains all over and a big hole in carpet



## **MISCELLANEOUS:**

Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok
Clear Storage Locker:	Ok
Closet Shelves:	Ok
Common Area damaged during moveout:	Ok
Door Intercom System:	Ok
Exhaust Fan:	Ok
Fan Blades:	Ok
Fire extinguisher:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Light Globes:	Ok
Mini Blind(s) each:	Ok
Outside Lights:	Ok
Phone Jack:	Ok
Rallings:	Ok
Removal Of Bulk Items:	Ok
Remove Debris (Per Bag):	Ok
Sliding Mirror/Glass Door (2):	Ok
Smoke Detector Alarm:	Ok
Stoppage by foreign object in any drain:	Ok
Switch Plate Covers:	Ok
Thermostat Cover:	Ok
Vertical Blinds:	Ok
Vinly Tile Bathroom:	Ok
Vinly Tile Kitchen:	Ok
Window Screen(s) each:	Ok
Window Sills:	Ok

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident	
Lindy Community Representative Name	Antonio Cordero

Technician	Antonio Cordero
Resident not available for signature	YES
Resident refused Signature	NO