



Make Ready Checklist Inspection

Inspection Date	Technician	Property	Units
08-11-2020	Kim Crawford	Mt. Airy Arms	212A

OVERALL:	
Signs of Moisture outside the apartment:	Ok
Signs of Moisture inside the apartment:	Ok
Resident	

Lindy Community Representative Name	Kim Crawford
-------------------------------------	--------------

Technician	Kim Crawford
Resident not available for signature	
Resident refused Signature	