



## Make Ready Checklist Inspection

Inspection Date	Technician	Property	Units
08-30-2020	Peter Tester	Meadowbrook	167

LIVING ROOM:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Window:	Ok
Door / Closet:	Ok
Window coverings:	Ok
Other:	Ok
Lindy Community Representative Name	Peter Tester

*Peter Tester*

Technician	Peter Tester
Resident not available for signature	
Resident refused Signature	