

## **Make Ready Checklist Inspection**

Inspection Date	Technician	Property	Units
09-15-2020	Chris Benitez	Towers at Wyncote	1203-3

LIVING ROOM:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Window:	Ok
Door / Closet:	Ok
Window coverings:	Ok
Other:	Ok
DINING ROOM:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Window:	Ok
Window coverings:	Ok
KITCHEN:	
Dishwasher Rack:	Not Ok
Charges Type	
Charges	0
Comment	Under rack the hinge needs cleaning



BEDROOMS:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Floors / Carpet:	Ok
Window:	Ok
Window coverings:	Ok
Door / Closet:	Ok
Other:	Ok
BATHROOM:	
Cleaning Bathroom:	Not Ok
Charges Type	
Charges	0
Comment	Tub needs to be cleaned again



Other:	Not Ok
Charges Type	
Charges	0
Comment	Tub stopper needs cleaning



LOCKS:	
Door Lock:	Ok

Door Knob:	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok
DOORS:	
Apartment Door:	Ok
Solid Core & Steel:	Ok
Frame:	Ok
Hollow:	Ok
PAINTING:	
Over Dark Colors (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Wallpaper Removal (Per Room):	Ok
Border Removal (Per Room):	Ok
CARPET:	
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
MISCELLANEOUS:	
Vertical Blinds:	Not Ok
Charges Type	
Charges	0
Comment	Living room blinds right side the 2nd & 3rd blinds are stuck together



OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok
Resident	Chris Benitez



Lindy Community Representative Name Chris E	Benitez
---	---------



	Technician	Chris Benitez
	Resident not available for signature	
	Resident refused Signature	