

## **Make Ready Checklist Inspection**

Inspection Date	Technician	Property	Units
09-16-2020	Chris Benitez	Towers at Wyncote	1214-3

LIVING ROOM:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Window:	Ok
Door / Closet:	Ok
Window coverings:	Ok
Other:	Ok
DINING ROOM:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Window:	Ok
Window coverings:	Ok
KITCHEN:	
Cabinet Shelf:	Not Ok
Charges Type	
Charges	0
Comment	Cabinet left of oven shelf fell down




BEDROOMS:	
Other:	Not Ok
Charges Type	
Charges	0
Comment	Master bedroom window - remove hook at the top of sill.



BATHROOM:	
Toilet Bowl:	Not Ok
Charges Type	
Charges	0
Comment	2nd BR - Clean bowl and floor below Master - clean bowl and fix right upper drawer - falls out when you pull it out.



Other:	Not Ok
Charges Type	
Charges	0
Comment	Clean vent in master bath



LOCKS:	
Door Lock:	Ok
Door Knob:	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok
DOORS:	
Apartment Door:	Ok
Solid Core & Steel:	Ok
Frame:	Ok
Hollow:	Ok
PAINTING:	
Over Dark Colors (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Wallpaper Removal (Per Room):	Ok
Border Removal (Per Room):	Ok
CARPET:	
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok

Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
MISCELLANEOUS:	
Remove Debris (Per Bag):	Ok
Comment	Re
Window Screen(s) each:	Not Ok
Charges Type	
Charges	0
Comment	Living room screen left side has a hole in it. Please replace.



Outside Lights:	Not Ok
Charges Type	
Charges	0
Comment	Remove gum on balcony



OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok
Resident	Chris Benitez



Lindy Community Representative Name

Chris Benitez



Technician	Chris Benitez
Resident not available for signature	
Resident refused Signature	