



## Make Ready Checklist Inspection

Inspection Date	Technician	Property	Units
12-14-2020	Kim Crawford	Sedgwick Gardens	D222

OVERALL:	
Signs of Moisture outside the apartment:	Ok
Signs of Moisture inside the apartment:	Ok
Resident	

Lindy Community Representative Name	Kim Crawford
-------------------------------------	--------------

Technician	Kim Crawford
Resident not available for signature	
Resident refused Signature	