



Make Ready Checklist Inspection

| Inspection Date | Technician | Property | Units |
|-----------------|--------------|---------------|-------|
| 12-30-2020 | Kim Crawford | Mt. Airy Arms | 212B |

| OVERALL: | |
|--|----|
| Signs of Moisture inside the apartment: | Ok |
| Signs of Moisture outside the apartment: | Ok |
| Resident | |

| | |
|-------------------------------------|--------------|
| Lindy Community Representative Name | Kim Crawford |
|-------------------------------------|--------------|

| | |
|--------------------------------------|--------------|
| Technician | Kim Crawford |
| Resident not available for signature | |
| Resident refused Signature | |