



## Move Out Inventory & Condition Form

Inspection Date	Technician	Property	Units
12-31-2020	Dave Kimmel	Meadowbrook	861

Resident Name	Stephanie Vasta
Forwarding Mailing Address	Not Available
Date Resident Turned in Keys	12-30-2020

Damage Summary				
Main Category	Sub Category	Charges Type	Note	Charges
LIVING ROOM	Walls / Outlets	Repair		\$0.00
Additional Damage Charges				
Total Charges				\$0.00

<b>LIVING ROOM:</b>	
Walls / Outlets:	Not Ok
Charges Type	Repair
Charges	
Comment	Living room ceiling has stains possibly from water from roof leak and the walls in the living room need to be painted all other rooms are good



Ceilings / Lights:	Ok
--------------------	----

Window:	Ok
Door / Closet:	Ok
Window coverings:	Ok
<b>OVERALL:</b>	
Signs of Moisture outside the apartment:	Ok
Signs of Moisture inside the apartment:	Ok
Resident	

Lindy Community Representative Name	Dave Kimmel
-------------------------------------	-------------



Two handwritten signatures are shown. The top signature is 'David' in a cursive script. The bottom signature is 'Dave Kimmel' in a more stylized, elongated cursive script.

Technician	Dave Kimmel
Resident not available for signature	YES
Resident refused Signature	NO