



Move Out Inventory & Condition Form

Inspection Date: 07-22-2019

Technician: Paul Oneto

Property: Meadowbrook


Units: 332

LIVING ROOM:

Walls / Outlets: Not Ok


Comment: Double paint all blue walls





KITCHEN:

Cleaning Refrigerator: Not Ok




BEDROOMS:

Walls / Outlets: Not Ok

Comment: Double paint. Green and brown walls





CARPET:

Replace Carpet 2 Bedroom: Not Ok





Technician: Paul Oneto

Resident not available for signature : Yes

Resident refused Signature : No