



Make Ready Checklist Inspection

Inspection Date: 09-04-2019


Technician: Rafael Soto Ocasio


Property: Meadowbrook

Units: 564

CLEANLINESS:


Swept / Mopped: Not Ok






Closets cleared: Not Ok







Frig /Stove clean: Not Ok






No personal items: Not Ok





Other: Not Ok





LIVING ROOM:

Walls / Outlets: Not Ok



Ceilings / Lights: Ok

Window: Ok

Window coverings: Ok

DINING ROOM:

Walls / Outlets: Ok

Ceilings / Lights: Ok

Window: Ok

Window coverings: Ok

KITCHEN:

Cabinets: Not Ok




Cabinet Door: Ok

Cabinet Handle: Ok

Counter Top: Ok

Refrigerator (Freezer): Not Ok




Kitchen Sink: Not Ok

Comment: Sink is oof the countertop




BEDROOMS:

Walls / Outlets: Not Ok



Ceilings / Lights: Ok

Floors / Carpet: Not Ok




Window: Not Ok

Comment: Screens are broken



Door / Closet: Not Ok




BATHROOM:

Mirror and Medicine Cabinet: Not Ok





Vanity Cabinet: Not Ok



Sink: Not Ok

Complete Toilet: Ok

Cleaning Bathroom: Not Ok





Technician: Rafael Soto Ocasio

Resident not available for signature :

Resident refused Signature :