



## Move Out Inventory & Condition Form

**Inspection Date:** 09-18-2019

**Technician:** Rafael Soto Ocasio

**Property:** Meadowbrook

**Units:** 629

**CLEANLINESS:**

Swept / Mopped: Ok

Closets cleared: Ok

Frig /Stove clean: Not Ok



**LIVING ROOM:**

Walls / Outlets: Ok

Ceilings / Lights: Ok

Window: Ok

Window coverings: Ok

**DINING ROOM:**

Walls / Outlets: Ok

Ceilings / Lights: Ok

Window: Ok

Window coverings: Ok

**KITCHEN:**

Cabinets: Ok

Cabinet Door: Ok

Cabinet Shelf: Ok

Cabinet Handle: Ok

Counter Top: Ok

Refrigerator (Freezer): Ok

Refrigerator (Shelf and Bars): Ok

Refrigerator (Drawers): Ok

Refrigerator Crisper Glass/Plastic: Ok

Cleaning Refrigerator: Not Ok



Microwave: Ok

Cleaning of Stove: Ok

Garbage Disposal: Ok

Rubber Stopper: Ok

Kitchen Sink: Ok

Faucet Knobs: Ok

Floors: Ok

Faucet: Ok

Ceiling Light Fixture: Ok

Washer/Dryer: Ok

Wall Outlets: Not Ok



**BEDROOMS:**

Walls / Outlets: Ok

Ceilings / Lights: Ok

Floors / Carpet: Ok

Window: Ok

Window coverings: Ok

Door / Closet: Not Ok







**BATHROOM:**

Mirror and Medicine Cabinet: Ok

Vanity Cabinet: Ok

Sink: Ok

Toilet Tank Cover: Ok

Toilet Tank: Ok

Toilet Bowl: Ok

Complete Toilet: Ok

Toilet Paper Holder: Ok

Shower Head: Ok

Tub Knob(s): Ok

Shower Curtain Bar: Ok

Towel Bar: Ok

Remove Mildew on Tiles: Ok

Cleaning Bathroom: Ok

Floors: Ok

Cabinets / Mirror: Ok

Is there signs of moisture from outside in the apartment?: Ok

**CARPET:**

Replace Carpet 1 Bedroom: Not Ok







Replace Carpet 2 Bedroom: Not Ok

Comment: Appears to be paint





**Technician:** Rafael Soto Ocasio

Resident not available for signature : Yes

Resident refused Signature : No