



Move Out Inventory & Condition Form

Inspection Date: 11-29-2019

Technician: Rafael Soto Ocasio

Property: Meadowbrook

Units: 974

CLEANLINESS:

Swept / Mopped: Ok

Closets cleared: Ok

Frig /Stove clean: Ok

No personal items: Ok

LIVING ROOM:

Walls / Outlets: Ok

Ceilings / Lights: Ok

Window: Ok

Door / Closet: Ok

Window coverings: Ok

DINING ROOM:

Walls / Outlets: Ok

Ceilings / Lights: Ok

Window: Ok

Window coverings: Ok

KITCHEN:

Cabinets: Ok

Cabinet Door: Ok

Cabinet Shelf: Ok

Cabinet Handle: Ok

Counter Top: Ok

Refrigerator (Freezer): Ok

Refrigerator (Shelf and Bars): Ok

Refrigerator (Drawers): Ok
Refrigerator Crisper Glass/Plastic: Ok
Cleaning Refrigerator: Ok
Dishwasher Rack: Ok
Dishwasher Silverware Holder: Ok
Dishwasher Knob: Ok
Fire Stops: Ok
Cleaning of Stove: Ok
Garbage Disposal: Ok
Oven Door Handle: Ok
Oven Racks: Ok
Kitchen Sink: Ok
Faucet Knobs: Ok
Floors: Ok
Faucet: Ok
Range Hood: Ok
Range Top: Ok
Ceiling Light Fixture: Ok
Ceiling Fan: Ok
Washer/Dryer: Ok
Wall Outlets: Ok
Window Coverings: Ok

BEDROOMS:

Walls / Outlets: Ok
Ceilings / Lights: Ok
Floors / Carpet: Ok
Window: Ok
Window coverings: Ok
Door / Closet: Ok

BATHROOM:

Medicine Cabinet: Ok
Vanity Cabinet: Ok
Sink: Ok
Toilet Tank Cover: Ok
Toilet Tank: Ok
Toilet Bowl: Ok

Complete Toilet: Ok

Shower Head: Ok

Shower Curtain Bar: Ok

Towel Bar: Ok

Counter Top: Ok

Soap Dish (Sink): Ok

Remove Mildew on Tiles: Ok

Cleaning Bathroom: Ok

Wall Outlets: Ok

Floors: Ok

Cabinets / Mirror: Ok

Is there signs of moisture from outside in the apartment?: Ok

DOORS:

Apartment Door: Ok

Solid Core & Steel: Ok

Frame: Ok

Hollow: Ok

Technician: Rafael Soto Ocasio

Resident not available for signature : Yes

Resident refused Signature : No