



Move Out Inventory & Condition Form

Inspection Date: 12-02-2019

Technician: Paul Oneto

Property: Meadowbrook

Units: 502

KITCHEN:

Cleaning Refrigerator: Not Ok





BEDROOMS:

Walls / Outlets: Not Ok

Comment: Black chalkboard paint one wall in bedroom



Floors / Carpet: Not Ok

Comment: Stains. Torn





DOORS:

Solid Core & Steel: Not Ok

Comment: Mirror closet door cracked





CARPET:

Shampoo 2 Bedroom: Not Ok

Comment: Stains all over






Stain Removal: Not Ok

Comment: Stains bedrooms and living room





Technician: Paul Oneto

Resident not available for signature : Yes

Resident refused Signature : No