

## **Move Out Inventory & Condition Form**

Inspection Date	Technician	Property	Units
03-19-2024	Nilsa Reyes	Joshua House	B0105

Approved By	Nilsa Reyes
Resident Name	Benetta Dorbor
Forwarding Mailing Address	2101 Glendale Ave Apt 307 Philadelphia PA 19152
Date Resident Turned in Keys	03-13-2024

Damage Summary				
Main Category	Sub Category	Charges Type	Note	Charges
KITCHEN	Formica/Tiles	Replace	kitchen floor will need to be replaced	\$840.00
BATHROOM	Cleaning Bathroom	Replace		\$0.00
BATHROOM	Floors	Replace	bathtub surround eft with sticky tile need to replace surround	\$510.00
BATHROOM	BATHROOM Remove Mildew on Tiles Replace		\$0.00	
Additional Damage Charges				
Total Charges			\$1350.00	

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

DINING ROOM:	
--------------	--

Ceilings / Lights:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok


KITCHEN:	
Backsplash:	Ok
Ceiling Fan:	Ok
Ceiling Light Fixture:	Ok
Ceiling Lights:	Ok
Cleaning of Stove:	Ok
Counter Top:	Ok

Dishwasher:	
Dishwasher Knob:	Ok

Dishwasher:	
Dishwasher Rack:	Ok

Dishwasher:		
Dishwasher Silverware Holder:		Ok
Drip Pan:	Ok	
Electric Meter:	Ok	
P	01-	

Electric Meter:	Ok
Faucet:	Ok
Faucet Knobs:	Ok
Floors:	Ok
Formica/Tiles:	Not Ok
Charges Type	Replace
Charges	
Comment	Stick tiles were placed over plank in kitchen



Monteners 85 Object 00			
Garbage Disposal:	Ok	Ok	
Kitchen Sink:	Ok	Ok	
Microwave:	Ok	Ok	
Other:	Ok	Ok	
Oven / Range:			
Oven Cleaning:		Ok	
Oven / Range:			
Oven door handle:		Ok	
Oven / Range:			
Oven drip pan:		Ok	
Oven / Range:			
Oven knobs:		Ok	
Oven / Range:			
Oven Racks:		Ok	
Oven / Range:			
Range burners:		Ok	
Oven / Range:			
Range Hood:		Ok	
Oven Door Handle:	Ok		
Oven Racks:	Ok		
Range Top:	Ok		
Rubber Stopper:	Ok	Ok	

Stove Knob:	Ok
Verify that either a Fire Stop (under the microwave) or FireAvert (behind the stove) exists.:	Ok
Wall Outlets:	Ok
Washer/Dryer:	Ok
Window Coverings:	Ok

BEDROOMS:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Floors / Carpet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok


BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Not Ok
Charges Type	Replace
Charges	
Comment	Bathroom stick tiles and surround was put up



Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Not Ok
Charges Type	Replace
Charges	



Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Remove Mildew on Tiles:	Not Ok
Charges Type	Replace
Charges	
Comment	Stick tiles put over ceramic tiles



Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Ok
Tub Knob(s):	Ok

Tub Reglazing:	Ok
Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok

KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok

DOORS:	
Apartment Door:	Ok
Apartment Door closes automatically:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

PAINTING:	
Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok

Shampoo 2 Bedroom:	Ok	
Stain Removal:	Ok	

MISCELLANEOUS:		
Broken Window Glass (Per Pane):		Ok
Cabinet Equipment:		Ok
Carbon Monoxide Detector:		Ok
Cleaning of Apartment:		Ok
Clear Storage Locker:		Ok
Closet Shelves:		Ok
Common Area damaged during moveout:		Ok
Door Intercom System:		Ok
Exhaust Fan:		Ok
Fan Blades:		Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:		Ok
Date of Installation		2021-03-19
Light Globes:		Ok
Mini Blind(s) each:		Ok
Outside Lights:		Ok
Phone Jack:		Ok
Rallings:		Ok
Removal Of Bulk Items:		Ok
Remove Debris (Per Bag):		Ok
Sliding Mirror/Glass Door (2):		Ok
Smoke Detector Alarm:		Ok
Stoppage by foreign object in any drain:		Ok
Switch Plate Covers:		Ok
Thermostat Cover:		Ok
Vertical Blinds:		Ok
Vinly Tile Bathroom:		Ok
Vinly Tile Kitchen:		Ok
Was personal property left behind?:		Yes
Estimated Value of Personal Property is.	\$0	1

Window Screen(s) each:		Ok
Window Sills:		Ok
OVERALL:		
Signs of Moisture inside the apartment:		Ok
Signs of Moisture outside the apartment:		Ok
Resident		
Lindy Community Dange ontative Name	Niles Daves	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name	Nilsa Reyes	
Lindy Community Representative Name  Technician	Nilsa Reyes	