



Make Ready Checklist Inspection

Inspection Date: 10-04-2019

Technician: Rafael Soto Ocasio

Property: Meadowbrook

Units: 518

CLEANLINESS:

Swept / Mopped: Ok

Closets cleared: Ok

Frig /Stove clean: Ok

No personal items: Ok

LIVING ROOM:

Walls / Outlets: Ok

Ceilings / Lights: Ok

Window: Ok

Door / Closet: Ok

Window coverings: Ok

DINING ROOM:

Walls / Outlets: Ok

Ceilings / Lights: Ok

Window: Ok

Window coverings: Ok

KITCHEN:

Cabinets: Ok

Cabinet Door: Ok

Cabinet Shelf: Ok

Cabinet Handle: Ok

Counter Top: Ok

Refrigerator (Freezer): Ok

Refrigerator (Drawers): Ok

Refrigerator Crisper Glass/Plastic: Ok

Cleaning Refrigerator: Ok

Dishwasher Rack: Ok

Dishwasher Silverware Holder: Ok

Dishwasher Knob: Ok

Fire Stops: Ok

Microwave: Ok

Cleaning of Stove: Ok

Garbage Disposal: Ok

Kitchen Sink: Ok

Faucet Knobs: Ok

Floors: Ok

Faucet: Ok

Ceiling Light Fixture: Ok

Ceiling Fan: Ok

Washer/Dryer: Ok

Wall Outlets: Ok

BEDROOMS:

Walls / Outlets: Ok

Ceilings / Lights: Ok

Floors / Carpet: Ok

Window: Ok

Window coverings: Ok

Door / Closet: Ok

BATHROOM:

Medicine Cabinet: Ok

Vanity Cabinet: Ok

Sink: Ok

Toilet Tank Cover: Ok

Toilet Tank: Ok

Toilet Bowl: Ok

Complete Toilet: Ok

Toilet Paper Holder: Ok

Shower Head: Ok

Shower Curtain Bar: Ok

Towel Bar: Ok

Tub Reglazing: Ok

Counter Top: Ok

Soap Dish (Sink): Ok

Remove Mildew on Tiles: Ok

Cleaning Bathroom: Ok

Wall Outlets: Ok

Floors: Ok

Cabinets / Mirror: Ok

Is there signs of moisture from outside in the apartment?: Ok

DOORS:

Apartment Door: Ok

Solid Core & Steel: Ok

Frame: Ok

Hollow: Ok

Technician: Rafael Soto Ocasio

Resident not available for signature :

Resident refused Signature :