



Make Ready Checklist Inspection

Inspection Date: 09-04-2019


Technician: Rafael Soto Ocasio

Property: Meadowbrook

Units: 564

CLEANLINESS:

Swept / Mopped: Not Ok







Closets cleared: Not Ok










No personal items: Not Ok






Other: Not Ok





LIVING ROOM:

Walls / Outlets: Not Ok



Ceilings / Lights: Ok

Window: Ok

Window coverings: Ok

DINING ROOM:

Walls / Outlets: Ok

Ceilings / Lights: Ok

Window: Ok

Window coverings: Ok

KITCHEN:

Cabinets: Not Ok



Cabinet Door: Ok

Cabinet Handle: Ok

Counter Top: Ok

Refrigerator (Freezer): Not Ok




Kitchen Sink: Not Ok

Comment: Sink is oof the countertop




BEDROOMS:

Walls / Outlets: Not Ok



Ceilings / Lights: Ok

Floors / Carpet: Not Ok



Window: Not Ok

Comment: Screens are broken




Door / Closet: Not Ok




BATHROOM:

Mirror and Medicine Cabinet: Not Ok






Vanity Cabinet: Not Ok



Sink: Not Ok



Toilet Tank Cover: Ok

Toilet Tank: Ok

Toilet Bowl: Ok

Complete Toilet: Ok

Cleaning Bathroom: Not Ok





Technician: Rafael Soto Ocasio

Resident not available for signature :

Resident refused Signature :