



Move Out Inventory & Condition Form

Inspection Date	Technician	Property	Units
02-26-2024	Daniel Ortiz	Meadowbrook	321

Resident Name	Maria Czebatul
Forwarding Mailing Address	Not Available
Date Resident Turned in Keys	Feb-23-2024

Amenities to be added to this Unit
Quartz Countertops
Updated Appliance Pkg

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

KITCHEN:	
Backsplash:	Ok
Cabinets:	Ok
Ceiling Fan:	Ok

Ceiling Light Fixture:	Ok
Ceiling Lights:	Ok
Cleaning of Stove:	Ok
Counter Top:	Ok
Dishwasher:	
Dishwasher Knob:	Ok
Dishwasher:	
Dishwasher Rack:	Ok
Dishwasher:	
Dishwasher Silverware Holder:	Ok
Drip Pan:	Ok
Electric Meter:	Ok
Faucet:	Ok
Faucet Knobs:	Ok
Floors:	Ok
Formica/Tiles:	Ok
Garbage Disposal:	Ok
Kitchen Sink:	Ok
Microwave:	Ok
Other:	Ok
Oven / Range:	
Oven Cleaning:	Ok
Oven / Range:	
Oven door handle:	Ok
Oven / Range:	
Oven drip pan:	Ok
Oven / Range:	
Oven knobs:	Ok

Oven / Range:		
Oven Racks:		Ok
Oven / Range:		
Range burners:		Ok
Oven / Range:		
Range Hood:		Ok
Oven Door Handle:		Ok
Oven Racks:		Ok
Range Top:		Ok
Refrigerator (Freezer):		
Cleaning Refrigerator:		Ok
Refrigerator (Freezer):		
Refrigerator (Drawers):		Ok
Refrigerator (Freezer):		
Refrigerator (Shelf and Bars):		Ok
Refrigerator (Freezer):		
Refrigerator Crisper Glass/Plastic:		Ok
Rubber Stopper:		Ok
Stove Knob:		Ok
Verify that either a Fire Stop (under the microwave) or FireAvert (behind the stove) exists.:		Ok
Wall Outlets:		Ok
Washer/Dryer:		Ok
Window Coverings:		Ok

BEDROOMS:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Floors / Carpet:	Not Ok
Charges Type	Replace
Charges	

Comment	Carpet was left with stains in multiple places of the carpet areas
---------	--



Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Ok
Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Ok
Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Ok

Tub Knob(s):	Ok
Tub Reglazing:	Not Ok
Charges Type	Repair
Charges	
Comment	Tub needs to be reglaze



Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok

KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok

Stain Removal:	Not Ok
Charges Type	Replace
Charges	
Comment	Carpet was left with stains




MISCELLANEOUS:	
Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok
Clear Storage Locker:	Ok
Closet Shelves:	Ok
Common Area damaged during moveout:	Ok
Door Intercom System:	Ok
Exhaust Fan:	Ok
Fan Blades:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Date of Installation	2024-02-23
Light Globes:	Ok
Mini Blind(s) each:	Ok

Outside Lights:	Ok		
Phone Jack:	Ok		
Rallings:	Ok		
Removal Of Bulk Items:	Ok		
Remove Debris (Per Bag):	Ok		
Sliding Mirror/Glass Door (2):	Ok		
Smoke Detector Alarm:	Ok		
Stoppage by foreign object in any drain:	Ok		
Switch Plate Covers:	Ok		
Thermostat Cover:	Ok		
Vertical Blinds:	Ok		
Vinly Tile Bathroom:	Ok		
Vinly Tile Kitchen:	Ok		
Was personal property left behind?:	Yes		
<table> <tr> <td>Estimated Value of Personal Property is.</td><td>\$0</td></tr> </table>		Estimated Value of Personal Property is.	\$0
Estimated Value of Personal Property is.	\$0		
Window Screen(s) each:	Ok		
Window Sills:	Ok		

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident	
<div></div>	
Lindy Community Representative Name	Daniel Ortiz



Technician	Daniel Ortiz
Resident not available for signature	YES
Resident refused Signature	NO