



Move Out Inventory & Condition Form

Inspection Date	Technician	Property	Units
04-11-2024	Daniel Ortiz	Meadowbrook	501

Resident Name	Marcella Vance
Forwarding Mailing Address	Not Available
Date Resident Turned in Keys	Apr-11-2024

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

KITCHEN:	
Backsplash:	Ok
Ceiling Fan:	Ok
Ceiling Light Fixture:	Ok
Ceiling Lights:	Ok
Cleaning of Stove:	Not Ok
Charges Type	Replace
Charges	

Comment

Stove was left dirty with dirty and damage glass top



Counter Top:

Ok

Dishwasher:

Dishwasher Knob:

Ok

Dishwasher:

Dishwasher Rack:

Ok

Dishwasher:

Dishwasher Silverware Holder:

Ok

Drip Pan:

N/A

Electric Meter:

Ok

Faucet:

Ok

Faucet Knobs:

Ok

Formica/Tiles:

N/A

Garbage Disposal:

Ok

Kitchen Sink:

Ok

Microwave:

Ok

Other:

Ok

Oven / Range:	
Oven Cleaning:	Not Ok
Charges Type	Clean
Charges	
Comment	Oven was left dirty



Oven / Range:	
Oven door handle:	Ok

Oven / Range:	
Oven drip pan:	N/A

Oven / Range:	
Oven knobs:	Ok

Oven / Range:	
Oven Racks:	Ok

Oven / Range:	
Range burners:	Not Ok
Charges Type	Replace
Charges	
Comment	Stove top was dirty and damaged



Oven / Range:	
Range Hood:	N/A

Oven Door Handle:	Ok
Oven Racks:	Ok
Range Top:	N/A
Rubber Stopper:	Ok
Stove Knob:	Ok
Verify that either a Fire Stop (under the microwave) or FireAvert (behind the stove) exists.:	Ok
Wall Outlets:	Ok
Washer/Dryer:	Not Ok
Charges Type	Clean
Charges	
Comment	Washer machine was left dirty



Window Coverings:

Ok

BEDROOMS:

Ceilings / Lights:

Ok

Door / Closet:

Ok

Floors / Carpet:

Not Ok

Charges Type

Replace

Charges

Comment

Carpet was left with urine smell and damage to it



Other:

Ok

Walls / Outlets:

Ok

Window:

Ok

Window coverings:

Ok

BATHROOM:

Cabinets / Mirror:

Ok

Ceiling Lights:

Ok

Cleaning Bathroom:

Ok

Complete Toilet:

Ok

Counter Top:

Ok

Floors:	Ok
Formica /Tile:	N/A
Is there signs of moisture from outside in the apartment?:	Ok
Other:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	N/A
Toilet Paper Holder:	Ok
Towel Bar:	Ok
Tub Knob(s):	Ok
Tub Reglazing:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok


KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok

DOORS:	
Apartment Door:	Ok
Apartment Door closes automatically:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

PAINTING:	
------------------	--

Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

MISCELLANEOUS:	
Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok
Clear Storage Locker:	Ok
Closet Shelves:	Ok
Common Area damaged during moveout:	Ok
Door Intercom System:	Ok
Exhaust Fan:	Ok
Fan Blades:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Date of Installation	2024-04-11
Light Globes:	Ok
Mini Blind(s) each:	Ok
Outside Lights:	Ok
Phone Jack:	Ok
Rallings:	Ok
Removal Of Bulk Items:	Ok
Remove Debris (Per Bag):	Ok
Sliding Mirror/Glass Door (2):	Ok
Smoke Detector Alarm:	Ok
Stoppage by foreign object in any drain:	Ok
Switch Plate Covers:	Ok
Thermostat Cover:	Ok
Vertical Blinds:	Ok
Vinly Tile Bathroom:	Ok
Vinly Tile Kitchen:	Ok
Was personal property left behind?:	Yes

Estimated Value of Personal Property is.	\$0
Window Screen(s) each:	Ok
Window Sills:	Ok
OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok
Resident	
Lindy Community Representative Name	Daniel Ortiz
	
Technician	Daniel Ortiz
Resident not available for signature	YES
Resident refused Signature	NO