

## **Move Out Inventory & Condition Form**

Inspection Date	Technician	Property	Units
06-30-2020	sharon waples	Crossings at Stanbridge	219

Resident Name	Dorothy Hodges
Forwarding Mailing Address	3588 Drifting Drive Hellertown,PA 18055
Date Resident Turned in Keys	Jun-30-2020

LIVING ROOM:		
Walls / Outlets:	Ok	
Ceilings / Lights:	Ok	
Window:	Ok	
Door / Closet:	Ok	
Window coverings:	Ok	
Other:	Ok	
DINING ROOM:		
Walls / Outlets:	Not Ok	
Charges Type	Repair	
Charges		
Comment Dining room wall near valueds to be replaced.		



Window: Ok

Window coverings:	Ok
KITCHEN:	
Electric Meter:	Ok
Cabinets:	Ok
Cabinet Door:	Ok
Cabinet Shelf:	Ok
Cabinet Handle:	Ok
Counter Top:	Ok
Refrigerator (Freezer):	Ok
Refrigerator (Shelf and Bars):	Ok
Refrigerator (Drawers):	Ok
Refrigerator Crisper Glass/Plastic:	Ok
Cleaning Refrigerator:	Not Ok
Charges Type	Clean
Charges	
Comment	Refrigerator needs to be cleaned




Dishwasher Rack:	Ok
Dishwasher Silverware Holder:	Ok
Dishwasher Knob:	Ok
Fire Stops:	Ok
Formica/Tiles:	Ok
Stove Knob:	Ok
Microwave:	Ok
Cleaning of Stove:	Not Ok
Charges Type	Clean
Charges	



Ceiling Lights:	Ok
Garbage Disposal:	Ok
Rubber Stopper:	Ok
Oven Door Handle:	Ok
Oven Racks:	Ok
Kitchen Sink:	Ok
Faucet Knobs:	Ok
Floors:	Ok
Faucet:	Ok
Drip Pan:	Ok
Range Top:	Ok
Ceiling Light Fixture:	Ok
Backsplash:	Ok
Ceiling Fan:	Ok
Wall Outlets:	Ok
Window Coverings:	Ok
Other:	Ok
BATHROOM:	
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Vanity Cabinet:	Ok
Sink:	Ok
Toilet Tank Cover:	Ok
Toilet Tank:	Ok
Toilet Bowl:	Ok

Complete Toilet:	Ok
Toilet Paper Holder:	Ok
Shower Head:	Ok
Tub Knob(s):	Ok
Shower Curtain Bar:	Ok
Towel Bar:	Ok
Tub Reglazing:	Ok
Counter Top:	Ok
Soap Dish (Sink):	Ok
Soad Dish (Tub):	Ok
Remove Mildew on Tiles:	Ok
Cleaning Bathroom:	Ok
Wall Outlets:	Ok
Ceiling Lights:	Ok
Floors:	Ok
Formica /Tile:	Ok
Cabinets / Mirror:	Ok
Window:	Ok
Other:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
LOCKS:	
Door Lock:	Ok
Door Knob:	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok
DOORS:	
Apartment Door:	Ok
Solid Core & Steel:	Ok
Frame:	Ok
Hollow:	Ok

PAINTING:		
Over Dark Colors (Per Room):	Ok	
Holes in Walls (Each Hole):	Ok	
Wallpaper Removal (Per Room):	Ok	
Border Removal (Per Room):	Ok	
CARPET:		
Replace Carpet 1 Bedroom:	Not Ok	
Charges Type	Replace	
Charges		
Comment	Bedroom carpet needs to be replaced.	



MISCELLANEOUS:	
Cleaning of Apartment:	Not Ok
Charges Type	Replace
Charges	
Comment	Living room carpet needs to be replaced.



Resident

Lindy	Community	Re	presei	ntative	Name
Liliay	Community	110	br cocr	ILLULIVC	TTUILL

sharon waples

Wyh

Technician	sharon waples
Resident not available for signature	YES
Resident refused Signature	NO