

## **Move Out Inventory & Condition Form**

Inspection Date	Technician	Property	Units
08-12-2024	Nilsa Reyes	Joshua House	B0106

Resident Name	Masjeda Nasher	
Forwarding Mailing Address	21931 Burbank Blvd unit 47 Woodland Hills CA 91367	
Date Resident Turned in Keys	Aug-09-2024	

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Walls / Outlets:	Not Ok
Charges Type	Replace
Charges	
Comment	Cover broken



Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Walls / Outlets:	Ok

Window:	Ok	Ok	
Window coverings:	Ok	Ok	
KITCHEN:			
Backsplash:		Ok	
Ceiling Fan:		Ok	
Ceiling Light Fixture:		Ok	
Ceiling Lights:		Ok	
Cleaning of Stove:		Ok	
Dishwasher:			
Dishwasher Knob:	Ok		

Dishwasher:	
Dishwasher Rack:	Ok

Dishwasher:	
Dishwasher Silverware Holder:	Ok
Drip Pan:	Ok
Faucet:	Ok
Faucet Knobs:	Ok
Floors:	Ok
Formica/Tiles:	Ok
Garbage Disposal:	Ok
Kitchen Sink:	Ok
Microwave:	N/A
Other:	Not Ok
Charges Type	Repair
Charges	
Comment	Walls written on



Oven / Range:		
Oven Cleaning:	Ok	
Oven / Range:		
Oven door handle:	Ok	
Oven / Range:		
Oven drip pan:	Ok	
Oven / Range:		
Oven knobs:	Ok	
Oven / Range:		
Oven Racks:	Ok	
Oven / Range:		
Range burners:	Ok	
Oven / Range:		
Range Hood:	Ok	
Oven Door Handle:		Ok
Oven Racks:		Ok
lange Top:		Ok
tubber Stopper:		Ok
itove Knob:		Ok
erify that either a Fire Stop (under the microwave) or FireAv	ert (behind the stove) exists.:	Ok
Vall Outlets:		Not Ok
Charges Type		Replace

Charges	
Comment	Need to replace




Washer/Dryer:	N/A	
Window Coverings:	Ok	

BEDROOMS:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Floors / Carpet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Ok
Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Ok
Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Remove Mildew on Tiles:	Ok

Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Not Ok
Charges Type	Replace
Charges	
Comment	Need to replace



Tub Knob(s):	Ok
Tub Reglazing:	Not Ok
Charges Type	Repair
Charges	
Comment	Will need to repair



Vanity Cabinet:	Ok
Wall Outlets:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok

Window:

Ok

KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok

DOORS:	
Apartment Door:	Ok
Apartment Door closes automatically:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

PAINTING:	
Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok

MISCELLANEOUS:	
Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok
Clear Storage Locker:	Ok
Closet Shelves:	Ok
Common Area damaged during moveout:	Ok
Door Intercom System:	Ok
Exhaust Fan:	Ok
Fan Blades:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Date of Installation	2020-05-12
Light Globes:	Ok
Mini Blind(s) each:	Ok
Outside Lights:	Ok
Phone Jack:	Ok
Rallings:	Ok
Removal Of Bulk Items:	Ok
Remove Debris (Per Bag):	Ok
Sliding Mirror/Glass Door (2):	Ok
Smoke Detector Alarm:	Ok
Stoppage by foreign object in any drain:	Ok
Switch Plate Covers:	Ok
Thermostat Cover:	Ok
Vertical Blinds:	Ok
Vinly Tile Bathroom:	Ok
Vinly Tile Kitchen:	Ok
Was personal property left behind?:	No
Charges Type	
Charges	0
Was the resident locked out?:	No
Charges Type	
Charges	0

Window Screen(s) each:	Ok
Window Sills:	Ok

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

|--|--|--|--|--|

L	Lindy Community Representative Name	Nilsa Reyes
"	Lindy Community Representative Name	Milsa Neyes

Technician	Nilsa Reyes
Resident not available for signature	YES
Resident refused Signature	NO