



Move Out Inventory & Condition Form



| Inspection Date | Technician | Property | Units |
|-----------------|-------------|-------------|-------|
| 12-31-2020 | Dave Kimmel | Meadowbrook | 861 |

| | |
|------------------------------|-----------------|
| Resident Name | Stephanie Vasta |
| Forwarding Mailing Address | Not Available |
| Date Resident Turned in Keys | Not Available |

| | |
|---------------------|--|
| LIVING ROOM: | |
| Walls / Outlets: | Not Ok |
| Charges Type | Repair |
| Charges | |
| Comment | Living room ceiling has stains possibly from water from roof leak and the walls in the living room need to be painted all other rooms are good |



| | |
|--|----|
| Ceilings / Lights: | Ok |
| Window: | Ok |
| Door / Closet: | Ok |
| Window coverings: | Ok |
| OVERALL: | |
| Signs of Moisture outside the apartment: | Ok |
| Signs of Moisture inside the apartment: | Ok |
| Resident | |

| | |
|---|-------------|
| Lindy Community Representative Name | Dave Kimmel |
|   | |
| Technician | Dave Kimmel |
| Resident not available for signature | YES |
| Resident refused Signature | NO |