



## Inventory & Condition Form

**Property:**

Towers at Wyncote

**Units:**

0909-1

**Interior moisture**

Yes

Comment: Tenant states water continues to come through bottom portion of master bedroom window:

**Clean Dryer Lint Trap**

Yes

**Fill with water to correct level**

Yes

**Is there a Fire Extinguisher Installed?**

Yes

**Is there a Smoke Detector Installed?**

Yes

**Are there Fire Stops?**

Yes

**Please rate the quality of housekeeping as good or poor.**

Good