

Print



Inventory & Condition Form

Property:

Haverford Court

Units:

W111

Resident:

Lensa Desta

Created By:

Jenika Fields

Changed air conditioning filters/Kitchen/Bath Vents

Yes

Does the apartment have a fire stop installed either over the stove or behind the stove?

Yes

Is there a fire extinguisher mounted under the kitchen sink along with a decal on how to operate?

Yes

Are all smoke detectors working?

Yes

Is there any damages to the unit?

No

Is there any leaks in the bathroom or bathroom toilet?

No

Is there any leaks in the Kitchen?

No

Are there any pets in the apt? If so please note how many and whether they are cats/dogs

No

Smoker?

No

Does the front door automatically close?

Yes

Hoarding

No

Pests

No

Interior moisture

No

Is there a Fire Extinguisher Installed?

Yes

Is there a Smoke Detector Installed?

Yes

Are there Fire Stops?

Yes

Please rate the quality of housekeeping as good or poor.

Good