

Print



Inventory & Condition Form

Property:

Crossings at Stanbridge

Units:

518

Resident:

Joe Loburak

Created By:

Ricardo Rodriguez

Changed air conditioning filters/Kitchen/Bath Vents

Yes

Does the apartment have a fire stop installed either over the stove or behind the stove?

Yes

Please rate the quality of housekeeping as good or poor.

Good

Is there a fire extinguisher mounted under the kitchen sink along with a decal on how to operate?

Yes

Are all smoke detectors working?

Yes

Is there any damages to the unit?

No

Is there any leaks in the bathroom or bathroom toilet?

No

Is there any leaks in the Kitchen?

No

Smoker?

N/A

Does the front door automatically close?

Yes

Hoarding

No

Pests

No

Interior moisture

No

Is there a Fire Extinguisher Installed?

Yes

Is there a Smoke Detector Installed?

Yes

Are there Fire Stops?

Yes