

Date	01-08-2020
Property	201-207 Leedom St.
Employee Name:	Sheila Crockett
Employee Name:	Sheila Crockett
Time In	03:15 PM
Time Out	05:15 PM

Areas Cleared	Parking Lot
Equipment Used	Salt Spreaders, Snow Plows
Snow melt used	
Enter pounds distributed	
Is the sidewalk totally clear of Snow and Ice?	Yes
If not, please explain	
Other notes	This is. Test log

