

Date	01-17-2018
Property	Crossings at Stanbridge
Employee Name:	Gilbert Antuna
Time In	05:30 AM
Time Out	07:30 AM

Areas Cleared	Sidewalk, Steps
Equipment Used	Salt Spreaders, Scrapers and Shovels
Snow melt used	Yes
Enter pounds distributed	Used 4 bags of salt
Is the sidewalk totally clear of Snow and Ice?	Yes
If not, please explain	
Other notes	

