



CREATED VIA WEB

Date	01-27-2026
Property	York House (South)
Company Name	M&M
Vendor Name	M&M
Employee Name:	Bob
Time In	10:13 AM
Time Out	10:38 AM

Outside Temperature (F)	20
Areas Cleared	Parking Lot
Equipment Used	Snow Plows, Salt Spreaders
Snow melt used	YES
Enter pounds distributed	300
Is the sidewalk totally clear of Snow and Ice?	YES
If not, please explain	
Other notes	Can't get through circle. Too many vehicles parked

