



Date	01-28-2022
Property	Crossings at Stanbridge
Employee Name:	Gilbert Antuna
Time In	09:30 AM
Time Out	10:30 AM

Areas Cleared	Sidewalk
Equipment Used	Snow Blowers, Scrapers and Shovels
Snow melt used	YES
Enter pounds distributed	250lb
Is the sidewalk totally clear of Snow and Ice?	YES
If not, please explain	
Other notes	