



Date	02-19-2021
Property	Elkins Park Terrace
Employee Name:	Reino contractor
Time In	05:00 PM
Time Out	05:20 PM

Areas Cleared	Sidewalk, Steps
Equipment Used	Snow Plows, Scrapers and Shovels, Salt Spreaders
Snow melt used	YES
Enter pounds distributed	This property was treated by Reino contractors I don't know how much snow melt was used on this property.
Is the sidewalk totally clear of Snow and Ice?	YES
If not, please explain	
Buildings Cleared	Building is cleared sidewalks and steps are cleared and treated. parking areas still needs to be clear.
Other notes	Steps and sidewalks are clear and treated

