



Date	12-14-2017
Property	Crossings at Stanbridge
Employee Name:	Gilbert Antuna
Time In	07:00 AM
Time Out	08:15 AM

Areas Cleared	Sidewalk, Steps
Equipment Used	Salt Spreaders, Scrapers and Shovels
Snow melt used	Yes
Enter pounds distributed	4 bags used
Is the sidewalk totally clear of Snow and Ice?	Yes
If not, please explain	
Other notes	

