



CREATED VIA WEB

Date	12-27-2025
Property	York North (YONO)
Company Name	M&M
Vendor Name	M&M
Employee Name:	Bob
Time In	07:12 AM
Time Out	07:49 AM

Outside Temperature (F)	29
Areas Cleared	Parking Lot
Equipment Used	Snow Plows, Salt Spreaders
Snow melt used	YES
Enter pounds distributed	650
Is the sidewalk totally clear of Snow and Ice?	NO
If not, please explain	No responsible.
Other notes	Plowed circle. Tried to plow lot wasn't plow able. Used extra salt

